

Job Hazard Analysis Form

Example No. 2

JOB TITLE: Grinding Operator
OPERATION: Cleaning No. Grinder
JOB LOCATION: Plastic Extrusion

DATE OF ANALYSIS:

STEP	HAZARD	NEW PROCEDURE OR PROTECTION
1. Shut off grinder, lockout and tagout	None	Follow company's LO/TO Program
2. Open clean-out door	Contact with cutting knives, airborne plastic dust	Wear cotton gloves and particulate dust mask
3. Open cutting chamber and take clamp off blower pipe	Door is heavy, overexertion	Use caution, 2 person job
4. Remove screen chamber	Heavy, could fall and cause damage	Should be removed by 2 persons
5. Remove screen	Contact with cutting knives	Wear cotton gloves
6. Clean all parts	Cutting knives, plastic dust	Wear cotton gloves and particulate dust mask
7. Clean cyclone and filter	Falling parts and plastic dust	Use cage attached to forks of forklift, use particulate mask
8. Install screen and cradle	Cutting knives, cradle is heavy	Wear cotton gloves, install cradle by 2 persons
9. Install chamber and clamp on blower pipe	Could fall and cause damage	Should be installed by 2 persons
10. Install clean out door and clean floor area	Cutting knives	Wear cotton gloves